

Connettore a Pressione
Push on Connector
Connecteur à Pression
Conector à Pressão




Conector a Pressión
Steckverbinder
Konektor Naciskany



**Connessione guidata
Assembly instruction
Connexion assistée
Instruções de montagem
Conexión guiada
Einbauanleitung
Instrukcja montażu**

Cavi con poca schermatura (40% di calza)
Cables with thin (40%) outer shield
Cables avec blindage réduit (40% de tresse)
Cabo com pouca blindagem (40% de malha)
Cables con poco blindaje (40% di alambres)
Kabel mit dünner (40%) äusserer Schirmung
Montaż na kablu z zadkim oplotem (40%)



Cavi con buona schermatura (80% di calza)
Cables with thick (80%) outer shield
Cables avec blindage épais (80% de tresse)
Cabo com boa blindagem (80% de malha)
Cables con buen blindaje (80% di alambres)
Kabel mit dünner (80%) äusserer Schirmung
Montaż na kablu z gestym oplotem (80%)





Taglio guaina
Cut sheath
Coupe gaine
Corte da cobertura
Corte funda
Kabelmantel entlang
Naciac koszulke w zdluz





Ripiegamento calza e guaina
Fold back outer shield and sheath
Replier tresse et gaine
Dobra da cobertura e da malha
Doblado blindaje y funda
äussere Abschirmung zurückbiegen
Odgiac izolacje i oplot do tyłu







Taglio del dielettrico e del conduttore centrale a 45°
Strip dielectric off and cut central conductor at 45°
Coupe du diélectrique et du conducteur central à 45°
Corte do dielétrico e do condutor central a 45°
Corte del dieléctrico y del conductor central à 45°
Dielektrikum abstreifen und Zentralader unter 45° abschneiden
Naciac dielektryk, przewod centralny przyciac pod katem 45°




Inserzione conduttore centrale su connettore F femmina
Insert central conductor in F-type female connector
Insertion du conducteur central sur la fiche F femelle
Introdução do condutor central no conector F fêmea
Insertion del conductor central sobre connector F hembra
Zentralader in die F-Buchse einführen
Wlozyc przewod centralny do konektora F




Inserzione CaP (non avitando)
Insert CaP (do not screw)
Insertion CaP (sans vissage)
Introdução do CaP (sem enroscar)
Inserción CaP (sin enroscar)
Einführung CaP (bitte nicht schrauben)
Nacisnac CaP (nie nakreccac)



**Scollegamento - Removal - Déconnexion - Desconexão
Desconexión - Demontage - Demontaz**



No - Non - Não - Nein - Nie



Si - Yes - Oui - Sim - Si - Ja - Tak